

RESERVE STUDIES

133 E. De La Guerra #195 Santa Barbara, CA 93101

PHONE: (805) 452-7212 Fax: (805) 832-6287 JD @ JDBROOKS.COM

> MEMBER OF COMMUNITY ASSOCIATIONS INSTITUTE



EUCALYPTUS GROVE HOA

GOLETA, CA

RESERVE STUDY REPORT: DECEMBER 28, 2022

RECOMMENDATIONS FOR THE BUDGET YEAR PERIOD FROM: JANUARY 1, 2023 THROUGH: DECEMBER 31, 2023

> COVER INTRODUCTION RESERVE STUDY SUMMARY

DEFINITIONS COLOR GRAPHS & CHARTS: THIRTY-YEAR RESERVE BALANCE PROJECTIONS RESERVE CATEGORY VALUES AS PERCENTAGE OF ALL COMPONENTS PROJECTED ANNUAL RESERVE EXPENSES

RESERVE COMPONENT INVENTORY THIRTY-YEAR PROJECTED ANNUAL RESERVE EXPENSES THIRTY-YEAR PROJECTED ANNUAL RESERVE BALANCES

> COLOR PHOTO DOCUMENTATION COMPONENT DESCRIPTIONS CALIFORNIA CIVIL CODE OVERVIEW

INTRODUCTION

This Reserve Study is an evaluation of the association's Common Area Components and their Reserve Funds. It was prepared after a thorough on-site inspection performed on: August 16, 2022

The goal is to keep the Reserve Funds at a sufficient level for future repair and/or replacement of these components and to disclose this information formally to the Association.

Eucalyptus Grove HOA

a condominium development consisting of thirteen: three-story buildings, plus a pool house, is located in: Goleta, CA

The community is comprised of 179 units built in 1985.

The Association's Fiscal Year End is December 31.

This study's Reserve Component Inventory lists the components that require reserve funding.

The Projected Reserve Fund Balance at Fiscal Year End 2022 is \$2,540,000. The Ideal Reserve Fund Balance at Fiscal Year End 2022 is \$3,261,927. Therefore, the Reserve Fund is theoretically <u>78%</u> Funded.

The Current (2022) <u>Annual</u> Reserve Contribution is set at approximately \$351,192. J.D. Brooks recommends increasing this Annual Reserve Contribution to \$389,856 (The Cash-Flow (Minimum) Contribution) for 2023, plus a contribution increase of 4% annually. This funding plan *should* keep the association's Reserve Fund above \$235,860 over a thirty-year period.

NOTE: This Funding Plan includes the assumption that all Interest earned on the Reserve Funds will be re-invested back into the Reserve Accounts (Net after Tax obligations)

The Repair / Replace Estimates and other parameters used in this study were estimated with the assistance of information obtained from one or more of the following:

- 1 The Association's Board of Directors.
- 2 The Association's Property Manager.
- 3 Vendor (Subcontractor) Proposal / Contract for work.
- 4 Vendor (Subcontractor) experience with the Association.
- 5 Construction estimating reference books & databases.
- 6 J.D. Brooks database of area construction costs and similar reserve studies.

This reserve study does not imply a warranty or guarantee of any form. The named Association, by receiving this study, agrees to release J.D. Brooks from any claims and/or lawsuits.



Reserve Stu		ARY	
Association Information: Name of Association: Location: Number of Units: Approximate Age of Complex:	EUCALYPT Goleta, CA 179 37	'US GROVE	НОА
This report recommends co Beginning: Ending:	ONTRIBUTIONS fo JANUARY 1, 20 DECEMBER 31,	23	ar:
Reserve Study Report Date: Current Fiscal Year End:	December 28, 2 December 31, 2		
CURRENT FUNDS SUMMARY: Projected Reserve Balance at Current Fi Ideal Reserve Balance at Current Fi PERCEN		\$2,540,000 \$3,261,927 78%	
CURRENT RESERVE CONTRIBUTIONS:	Annual	Monthly	Monthly Per Unit
2022 Budgeted Reserve Contribution	\$351,192	\$29,266	\$163.50
RECOMMENDATIONS F	or Budget Y	ZEAR 2023	
RESERVE CONTRIBUTION MODELS: 2023 J.D. Brooks Recommendation in Box	Annual	Monthly	Monthly Per Unit

2023 Straight-Line Contribution:	\$409,679	\$34,140	\$190.73
2023 Deficit Reduction Contribution:	\$476,202	\$39,684	\$221.70
2023 Cash-Flow (Minimum) Contribution:	\$389,856	\$32,488	\$181.50

<u>J</u> .	D.	BRC	DOKS

RESERVE STUDIES

RESERVE STUDY DEFINITIONS

AVG. NET INTEREST ON RESERVE SAVINGS:

Average amount (after tax) of interest re-invested into the Reserve Account CASH-FLOW (MINIMUM) CONTRIBUTION:

Calculated by not allowing the Reserve Balance to ever fall below (5% of the Total Replacement Cost of all the components) over a thirty-year period.

This Funding Plan should keep the Reserve Fund Balance just above \$0.

DEFICIT REDUCTION ANNUAL CONTRIBUTION:

Equals (the Straight-Line Annual Contribution) plus {(the Underfunded Balance if any) divided by (the Remaining Life)}.

F.Y.E. (FISCAL YEAR END):

End of the accounting budget year.

IDEAL BALANCE AT F.Y.E.:

Equals (the Straight-Line Annual Contribution) multiplied by (the age) of the component. **30-YEAR AVERAGE INFLATION RATE:**

Average Inflation Rate for the full 30-Year Forecast.

PERCENT FUNDED:

Equals (the Projected Reserve Balance at Fiscal Year End) divided by (the Ideal Reserve Balance at Fiscal Year End).

PROJECTED BALANCE AT F.Y.E.:

Projected Reserve Balances for each Reserve Component. Calculated according to priority (need) of replacement.

RESERVE COMPONENT:

Common Area item that requires replacement within thirty-years.

RMNG. LIFE (REMAINING LIFE):

Life-span remaining for the Reserve Component.

STRAIGHT-LINE ANNUAL CONTRIBUTION:

Equals (the Repair/Replace Cost) divided by (the Useful Life).

SURPLUS / DEFICIT:

Equals (the Ideal Balance at F.Y.E.) minus (the Projected Balance at F.Y.E.).

UNIT COST:

Cost per unit of measure.

UNIT TYPE:


Unit of measure.

USEFUL LIFE:


Expected life-span of the Reserve Component.




EUCALYPTUS GROVE HOA



EUCALYPTUS GROVE HOA





				EUCAL	PTUS	GR	OVE HOA				
RESERVE COMPONENT			_				BER 31, 2022	-			
INVENTORY				NUMBER O							
CATEGORY	_	Unit	Unit	Repair / Replace	USEFUL		Straight-Line Annual	IDEAL BALANCE	Projected Balance	_	DEFICIT REDUCTION ANNUAL
RESERVE COMPONENT	QUANTITY	' TYPE	Cost	Cost	LIFE	LIFE	CONTRIBUTION	@F.Y.E.2022	@F.Y.E.2022	DEFICIT	CONTRIBUTION
ROOFING											
Сомр.S:7626,7630,7634	з	BLDG.	39000	117,000	25	9	4,680	79,560	-	(79,560)	13,520
Сомр.S: 7624, 7628	2	BLDG.	39000	78,000	25	12	3,120	43,680	-	(43,680)	6,760
Сомр.S: 7636, 7638	2	BLDG.	39000	78,000	25	13	3,120	40,560	-	(40,560)	6,240
Сомр.S:7602,7606,7610	3	BLDG.	39000	117,000	25	14	4,680	56,160	-	(56,160)	8,691
Сомр.S:7620,7632,7640	3	BLDG.	39000	117,000	25	15	4,680	51,480	-	(51,480)	8,112
COMP.S: POOL CABANA	1	BLDG.	5800	5,800	25	15	232	2,552	-	(2,552)	402
METAL CARPORTS	30,000	SQFT	9.20	276,000	30	1	9,200	276,000	276,000	-	9,200
GUTTER & DOWNSPOUTS	7,200	LNFT	11.00	79,200	30	27	2,640	10,560	-	(10,560)	3,031
PAINTING											
WOOD SIDING	120,000	SQFT	1.40	168,000	6	2	28,000	140,000	140,000	-	28,000
WOOD & METAL TRIM	35,000	SQFT	2.10	73,500	4	2	18,375	55,125	55,125	-	18,375
CARPORTS	60,000	SQFT	1.60	96,000	6	2	16,000	80,000	80,000	-	16,000
Metal Fence & Rail	4,000	SQFT	1.60	6,400	4	1	1,600	6,400	6,400	-	1,600
FRONT WOOD FENCE	600	LNFT	11.50	6,900	4	4	1,725	1,725	1,725	-	1,725
WOOD DRY ROT REPAIRS	1	ALLOW	480000	480,000	4	2	120,000	360,000	360,000	-	120,000
WOOD SIDING REPLACE	1	ALLOW	454500	454,500	20	3	22,725	409,050	409,050	-	22,725
	INTERIOF	R PAINT	ING OPE	RATING MAI	NTENANC	E EXPEN	SE				
PAVING											
ASPHALT SEAL & REPAIR	120,000	SQFT	0.22	26,400	З	1	8,800	26,400	26,400	-	8,800
ASPHALT OVERLAY	120,000	SQFT	2.20	264,000	25	22	10,560	42,240	-	(42,240)	12,480
CONCRETE REPAIRS	1	ALLOW	65000	65,000	5	1	13,000	65,000	65,000	-	13,000
DECKING					_	_					
STAIR LANDING RESEAL	4,600	-	6.00	27,600	5	1	5,520	27,600	27,600	-	5,520
STAIR LANDING RESURFACE	4,600	•	11.50	52,900	20	1	2,645	52,900	52,900	-	2,645
MID-LANDINGS> TREX		ALLOW	1000	7,000	30	1	233	7,000	7,000	-	233
TREX MID-LANDINGS		ALLOW	1000	24,000	30	24	800	5,600	-	(5,600)	1,033
	PRIVATE	BALCO	NY SURI	FACES INDI	VIDUAL H	OMEOWN	IER'S EXPENSE				
PRIVACY / FENCING						-				(0.000)	
INTERCOM	-	UNIT	6200	6,200	15	9	413	2,893		(2,893)	735
FRONT GATE WIRING	1	ALLOW	9000	9,000	10	6	900	4,500	4,294	(206)	934
GATE OPERATORS (ROLL)		UNIT	4000	8,000	10	6	800	4,000	3,817	(183)	
VEHICLE ROLL GATES	2	•••••	4600	9,200	30	5	307	7,973	7,973	-	307
KEY FOB READERS	3		2800	8,400	12	4 2	700 320	6,300	6,300	-	700 320
GATE KEYPADS			2400	4,800	15			4,480	4,480	-	- · · · -
FRONT WOOD FENCE		LNFT	200	120,000	20	20	6,000	6,000	-	(6,000) (E E 4 4)	6,300
METAL POOL FENCE 6'	180		70.00	12,600	25 30	15 7	504	5,544	-	(5,544)	874
STAIR RAILS 3.5'	500	LNFT	38.00	19,000	30	/	633	15,200	-	(15,200)	2,805



				EUCAL	YPTUS	s Gr	OVE HOA				
RESERVE COMPONENT INVENTORY			CURREN	T FISCAL YE NUMBER O			BER 31, 2022				
CATEGORY Reserve Component	QUANTITY	Unit Type	Unit Cost	Repair / Replace Cost	Useful Life		Straight-Line Annual Contribution	IDEAL Balance @F.Y.E.2022	Projected Balance @F.Y.E.2022	DEFICIT	DEFICIT REDUCTION ANNUAL CONTRIBUTION
WOOD RAIL FENCE	450	LNFT	24.00	10,800	30	12	360	6,840	-	(6,840)	930
PATIO UTILITY DOORS	472	Unit	500	236,000	45	8		199,289	-	(199,289)	30,156
	TRASH G	ATES C	PERATIN	g Maintena	NCE EXPI	ENSE					
POOL AREA			4600	4 600		2	676	4.005	4.005		F7F
POOL HEATER		UNIT	4600	4,600	8			4,025	4,025	-	575
POOL FILTER	1	•••••	2500 2200	2,500	12			1,667	1,667	-	208
POOL & SPA PUMPS	3			6,600	8	-		4,950	4,950	-	825
POOL FIBERGLASS	1,000		17.00	17,000	18			14,167	14,167	-	944
POOL TILE/COPING		LNFT	58.00	5,800	20	-		4,350	4,151	(199)	323
SPA HEATER		UNIT	4600	4,600	8			2,875	2,875	-	575
SPA FILTER		UNIT	2300	2,300	12			1,150	-	(1,150)	356
SPA RE-TILE		UNIT	8700	8,700	40			8,265	8,265	-	218
POOL DECKING	1	ALLOW	15600	15,600	20	6	780	11,700	11,165	(535)	869
CABANA											
SHOWER TILE	1	ALLOW	10000	10,000	30	1	333	10,000	10,000	-	333
BATH TILE	1	ALLOW	14000	14,000	30	28	467	1,400	-	(1,400)	517
BATHROOMS REMODEL	2	ALLOW	5000	10,000	30	4	333	9,000	9,000	-	333
SAUNA REMODEL	1	ALLOW	7200	7,200	20	15	360	2,160	-	(2,160)	504
Sauna Heater	1	UNIT	3800	3,800	20	11	190	1,900	-	(1,900)	363
WATER HEATER	1	UNIT	2300	2,300	15	11	153	767	-	(767)	223
TERMITE TREATMENTS											
BLDG, 7606	1	ALLOW	8900	8.900	15	12	593	2.373	-	(2,373)	791
BLDG. 7620, 7632	-	ALLOW	8900	17,800	15			4,747	-	(4,747)	1,582
BLDG, 7610, 7602		ALLOW	8900	17,800	15		, –	4,747	-	(4,747)	,
BLDG. 7638, 7630		ALLOW	8900	17,800	15		1,187	5,933	-	(5,933)	1,726
BLDG, 7634, 7628		ALLOW	8900	17.800	15		1,187	5,933	-	(5,933)	,
BLDG. 7626	1	ALLOW	8900	8,900	15		•	7,713	7,713	(0,000)	593
BLDG.7636,7640,7624	-	ALLOW	8900	26.700	15	-	1,780	26,700	26,700	-	1,780
				,,			,	· · - ,	,		, – –
FOUNDATION REPAIRS		_						~ ~ ~ ~ ~			
WATERPROOFING			224000	224,000	30		,	82,133		(82,133)	11,573
FOUNDATION LEVELING	1	ALLOW	108000	108,000	40	1	2,700	108,000	108,000	-	2,700
BALCONY INSPECTIONS	1	ALLOW	43000	43,000	9	2	4,778	38,222	38,222	-	4,778
STRUCTURAL PLUMBING											
PLUMBING REPAIRS PARTIAL	1	ALLOW	110800	110,000	35	1	3,143	110,000	110,000	-	3,143
PLUMBING REPAIRS BALANCE			612500	612,000	35		,	524,571	500,569	(24,002)	21,486
I LONDING I'LI AINS DALANCE	1		5.2500	0.2,000		0	17,400	SE-7,571	550,505	(,002)	21,400



				EUCAL	PTUS	6 GR	OVE HOA	L			
RESERVE COMPONENT INVENTORY			CURREN	T FISCAL YE		DECEM	BER 31, 2022				
CATEGORY RESERVE COMPONENT	QUANTITY	Unit Type	Unit Cost	REPAIR / REPLACE Cost		RMNG.	Straight-Line Annual Contribution	IDEAL Balance @F.Y.E.2022	Projected Balance @F.Y.E.2022	DEFICIT	DEFICIT REDUCTION ANNUAL CONTRIBUTION
BRIDGE REPAIRS	1	ALLOW	16200	16,200	10	8	1,620	4,860	-	(4,860)	2,228
TREE TRIMMING	2	ALLOW	22500	45,000	2	2	22,500	22,500	22,500	-	22,500
EXERCISE ROOM REMODEL EQUIPMENT	-	Allow Allow	30000 20000	30,000 20,000	20 10	20 10	1,500 2,000	1,500 2,000	-	(1,500) (2,000)	1,575 2,200
LIGHTING Large Street Fixtures Staircase LED Fixtures Carport Lights Medium Bollard Lights	14 1 64 50		3200 16000 200 250	44,800 16,000 12,800 12,500	30 25 25 25	28 22 1 5	1,493 640 512 500	4,480 2,560 12,800 10,500	12,800 10,500	(4,480) (2,560) - -	1,653 756 512 500
MAILBOXES MAILBOXES & PAGODAS	200	Unit	200	40,000	30	1	1,333	40,000	40,000	-	1,333
LANDSCAPE REFURBISH	1	ALLOW	88000	88,000	3	2	29,333	58,667	58,667	-	29,333
CONTINGENCY: 0%	-			& VALVES()PERATING M		-	ENANCE EXPEN ENSE -	SE -		-	
TOTALS:				4,717,200			409,679	3,261,927	2,540,000	(721,927)	476,202



						EU	CALY	PTU	s GR	OVE I	HOA					
RESERVE COMPONENT																
INVENTORY							D			D			~			
					<u>I HIRT</u>	<u>Y-YEAR</u>	PROJE	CTED A	NNUAL	KESER		PENSES	5			
CATEGORY	0	1	2	з	4	5	6	7	8	9	10	11	12	13	14	15
RESERVE COMPONENT	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037
ROOFING																
Сомр.S:7626,7630,7634	-	-	-	-	-	-	-			166,527			-			
COMP.S: 7624, 7628	-	-		-						, - · ·			124,881	-	-	
COMP.S: 7636, 7638	-	-	-	-		-	-				-		-	129,876	-	
COMP.S:7602,7606,7610	-	-		-						-			-	-	202,606	
COMP.S:7620,7632,7640	-	-	-	-		-	-				-		-	-	· -	210,710
COMP.S: POOL CABANA	-	-	-	-		-	-				-		-	-	-	10,445
METAL CARPORTS	-	287,040	-	-	-	-	-		-	-	-	-	-		-	
GUTTER & DOWNSPOUTS	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
PAINTING																
WOOD SIDING	-	-	181,709	-	-	-	-		229,920	-			-		290,922	
WOOD & METAL TRIM	-	-	79,498	-	-	-	93,001			-	108,798				127,278	-
CARPORTS	-	-	103,834	-	-	-			131,383	-		-	-		166,241	-
Metal Fence & Rail	-	6,656		-	-	7,787	-			9,109				10,656		-
FRONT WOOD FENCE	-	.,	-	-	8,072	,	-		9,443	.,	-	-	11,047		-	-
WOOD DRY ROT REPAIRS	-	-	519,168	-	-	-	607,353	-	-	-	710,517	-		-	831,205	-
WOOD SIDING REPLACE	-	-	-	511,251	-	-	-	-	-	-	-	-	-	-	-	-
PAVING																
ASPHALT SEAL & REPAIR	-	27,456	-	-	30,884	-	-	34,741	-	-	39,078	-	-	43,958	-	-
ASPHALT OVERLAY	-	,	-	-		-	-		-	-		-	-	,		-
Concrete Repairs	-	67,600	-	-		-	82,246	-	-	-	-	100,065	-	-		
DECKING																
STAIR LANDING RESEAL	-	28.704	-	-	-	-	34,923		-	-	-	42.489	-		-	-
STAIR LANDING RESERL	-	28,704 55,016	-	-	-	-			-	-		2,409	-		-	-
MID-LANDINGS -> TREX	-	7,280	-	-	-	-	-	-	-	-	-	-	-		-	-
TREX MID-LANDINGS			-	-	-	-	-	-	-	-	-	-	-	-	-	-
PRIVACY / FENCING																
	-	-	-	-	-	-	-	-	-	8,825	-	-	-	-	-	-
FRONT GATE WIRING	-	-	-	-	-	-	11,388	-	-	-	-		-	-	-	-
GATE OPERATORS (ROLL)	-	-	-	-	-	-	10,123	-	-	-	-		-	-	-	
VEHICLE ROLL GATES	-	-	-	-	-	11,193	-	-	-	-	-	-	-	-	-	-
KEY FOB READERS	-	-	-	-	9,827	-	-	-	-	-	-	-	-	-	-	-
GATE KEYPADS	-	-	5,192	-	-	-	-	-	-	-	-	-	-	-	-	-
FRONT WOOD FENCE	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
METAL POOL FENCE 6'	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	22,692
STAIR RAILS 3.5'	-	-	-	-	-	-	-	25,003	-	-	-	-	-	-	-	-

FUCAL VOTUS COOVE LOA

J.D. BROOKS RESERVE STUDIES

1	2/	2	8/	2	0	22
---	----	---	----	---	---	----

EUCALYPTUS GROVE HOA

							<u> </u>									
Reserve Component Inventory																
					THIRTY	-YEAR	Proje	CTED Å	<u>NNUAL</u>	Reser	VE EXF	PENSES	<u>5</u>			
CATEGORY	ο	1	2	З	4	5	6	7	8	9	10	11	12	13	14	15
RESERVE COMPONENT	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037
WOOD RAIL FENCE	-	-	-	-	-		-	-	-	-	-	-	17,291	-	-	
PATIO UTILITY DOORS	-	-	-	-	-	-	-	-	322,982	-	-	-	-	-	-	
POOL AREA																
POOL HEATER	-		4,975	-	-		-	-	-	-	6,809			-		
POOL FILTER	-		-	-	-	3,042	-	-	-	-	-			-		
POOL & SPA PUMPS	-	-	-	7,424	-	-	-		-	-	-	10,160	-	-	-	-
POOL FIBERGLASS	-	-	-	· -	19,888	-	-		-	-	-	· -	-	-	-	-
POOL TILE/COPING	-		-	-	-	-	7,339	-	-	-	-	-	-	-		-
Spa Heater	-	-	-	-	5,381	-	-		-	-	-	-	7,365	-	-	-
Spa Filter	-	-	-		-	-	-	3,027		-		-	-	-		-
SPA RE-TILE	-	-	-	9,786	-	-	-	-		-		-	-	-		-
POOL DECKING	-	-	-	-	-	-	19,739	-	-	-	-	-	-	-	-	
ABANA																
SHOWER TILE	-	10,400	-	-	-	-	-	-	-	-	-	-	-	-	-	-
BATH TILE	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-
BATHROOMS REMODEL	-	-	-	-	11,699	-	-	-	-	-	-	-	-	-		-
SAUNA REMODEL	-	-	-	-	-	-	-		-	-	-	-	-	-	-	12,96
Sauna Heater	-	-	-	-	-	-	-	-	-	-	-	5,850	-	-		-
WATER HEATER	-	-	-	-	-	-	-	-	-	-	-	3,541	-	-	-	-
ERMITE TREATMENTS																
Bldg. 7606	-	-	-	-	-	-	-	-	-	-	-	-	14,249	-	-	-
Bldg. 7620, 7632	-	-	-	-	-	-	-	-	-	-	-	-	28,498	-	-	-
Bldg. 7610, 7602	-	-	-	-	-	-	-	-	-	-	-	-	28,498	-	-	-
Bldg. 7638, 7630	-	-	-	-	-	-	-	-	-	-	-	27,402	-	-	-	-
Bldg. 7634, 7628	-	-	-	-	-	-	-		-	-	-	27,402	-	-		-
Bldg. 7626	-	-	-	10,011	-	-	-		-	-	-	-	-	-		-
Bldg.7636, 7640, 7624	-	27,768	-	-	-	-	-	-	-	-	-	-	-	-	-	-
OUNDATION REPAIRS																
WATERPROOFING	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
FOUNDATION LEVELING	-	112,320	-	-	-	-	-	-	-	-	-	-	-	-	-	-
ALCONY INSPECTIONS	-	-	46,509	-	-	-			-	-	-	66,197	-	-	-	-
TRUCTURAL PLUMBING																
PLUMBING REPAIRS PARTIAL	-	114,400	-	-	-	-	-	-	-	-	-	-	-	-	-	-



	=				THIRTY	(-YEAR	PROJEC	CTED A	NNUAL	Reser		PENSES	<u>3</u>			
ATEGORY Reserve Component	0 2022	1 2023	2 2024	3 2025	4 2026	5 2027	6 2028	7 2029	8 2030	9 2031	10 2032	11 2033	12 2034	13 2035	14 2036	15 203
RIDGE REPAIRS	-	-	-	-	-	-	-	-	22,171	-	-	-	-	-	-	
REE TRIMMING	-	-	48,672	-	52,644	-	56,939	-	61,586	-	66,611	-	72,046	-	77,925	
XERCISE ROOM																
Remodel	-	-	-	-		-	-		-	-	-	-	-	-	-	
EQUIPMENT	-	-	-	-	-	-	-	-	-	-	29,605	-	-	-	-	
GHTING																
Large Street Fixtures	-	-	-	-		-	-	-	-	-	-	-	-	-	-	
STAIRCASE LED FIXTURES	-	-	-	-		-	-	-	-	-	-	-	-	-	-	
CARPORT LIGHTS	-	13,312	-	-	-	-	-	-	-	-	-	-	-	-	-	
MEDIUM BOLLARD LIGHTS	-	-	-	-	-	15,208	-	-	-	-	-	-	-	-	-	
AILBOXES																
MAILBOXES & PAGODAS	-	41,600	-	-	-	-	-	-	-	-	-	-	-	-	-	
NDSCAPE REFURBISH	-	-	95,181	-		107.065	-	-	120,434	-	-	135,472	-	-	152,388	

CONTINGENCY: 0%	ENCY: 0%
-----------------	----------

TOTALS:	0 799,552 1,084,737 538,472 1	138,394 144,295 1,697,425	62,770 897,918 184,461	961,419 418,578	303,876 184,490 1,848,565 256,815

Г



RESERVE COMPONENT															
INVENTORY				_											
				<u>TH</u>	IRTY-YE	AR PRO	JECTEL	<u>ANNUA</u>	<u>AL RESE</u>	RVE E	<u>XPENS</u>	<u>ES</u>			
CATEGORY	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
RESERVE COMPONENT	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052
ROOFING															
Сомр.S:7626,7630,7634	-	-	-	-	-	-	-		-	-	-	-	-	-	-
Сомр.S: 7624, 7628	-	-	-	-	-	-	-		-	-	-	-	-	-	-
Сомр.S: 7636, 7638	-	-	-	-	-	-	-		-	-	-	-	-	-	-
Сомр.S:7602,7606,7610	-	-	-	-	-	-	-		-	-	-	-	-	-	-
Сомр.S:7620,7632,7640	-	-	-	-	-	-	-		-	-	-	-	-	-	-
COMP.S: POOL CABANA	-	-	-	-	-	-	-		-	-	-	-	-	-	-
METAL CARPORTS	-	-	-	-	-	-	-		-	-	-	-	-	-	-
GUTTER & DOWNSPOUTS	-	-	-	-	-	-	-	-	-	-	-	228,363	-	-	-
PAINTING															
WOOD SIDING	-	-	-	-	368,109	-	-		-	-	465,775	-	-		
WOOD & METAL TRIM		-	148,898	-	-		174,189		-	-	203,777	-	-		238,390
CARPORTS	-	-	-,	-	210,348	-	-		-	-	266,157	-	-		-
METAL FENCE & RAIL	-	12,467	-	-	· -	14,584	-		-	17,061	-	-	-	19,959	
FRONT WOOD FENCE	12,924	-	-	-	15,119	-	-		17,687	-	-	-	20,691	-	
WOOD DRY ROT REPAIRS	-	-	972.392	-	-		1,137,561	-		-	1,330,785	-	-		1,556,831
WOOD SIDING REPLACE	-	-	-	-	-	-	-	1,120,213	-	-	-		-	-	-
PAVING															
ASPHALT SEAL & REPAIR	49,447	-	-	55,621	-	-	62,566	•	-	70,378	-	-	79,166	-	-
ASPHALT OVERLAY	-	-	-	-	-	-	625,659	•	-	-	-	-	-	-	-
CONCRETE REPAIRS	121,744	-	-	-	-	148,120	-	-	-	-	180,211	-	-	-	-
DECKING															
STAIR LANDING RESEAL	51,694	-	-	-	-	62,894	-		-	-	76,520	-	-	-	-
STAIR LANDING RESURFACE	-	-	-	-	-	120,547	-	-	-	-	-	-	-	-	-
Mid-Landings> Trex	-	-	-	-	-	-	-		-	-	-	-	-	-	-
Trex Mid-Landings	-	-	-	-	-	-	-	-	61,519	-	-	-	-	-	-
PRIVACY / FENCING															
INTERCOM									15 000						
INTERCOM FRONT GATE WIRING		-	-	-	-	•	-	-	15,892	-		-	-	-	-
GATE OPERATORS (ROLL)	16,857	-	-	-	-	-	-	-	-	-	24,952	-	-	-	-
VEHICLE ROLL GATES	14,984	-	-	-	-	-	-	-	-	-	22,180	-	-	-	-
		-	-	-	-	•	-	-	-	-	-	-		-	-
KEY FOB READERS	15,733		-	-	-		-	-	-	-	-	-	25,189	-	-
GATE KEYPADS	-	9,350	-	-			-	-	-	-	-	-	-	-	-
FRONT WOOD FENCE	-	-	-	-	262,935	-	-	-	-	-	-	-	-	-	-
METAL POOL FENCE 6'	-	-	-	-	-		-	-	-	-	-	-	-	-	-
STAIR RAILS 3.5'	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-



12/28/2022

RESERVE COMPONENT

J.D. BROOKS

					-						-				
RESERVE COMPONENT															
INVENTORY										_					
				<u>TH</u>	IRTY-YE	AR PRC	JECTEL	<u>ANNU</u>	AL RESI	<u>erve E</u>	<u>XPENS</u>	<u>ES</u>			
CATEGORY	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
RESERVE COMPONENT	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052
WOOD RAIL FENCE	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
PATIO UTILITY DOORS	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
POOL AREA															
POOL HEATER	-	-	9,319	-			-		-	-	12,753	-	-	-	-
POOL FILTER		4,870	-,				-		-		,		-	7,797	-
POOL & SPA PUMPS	-	-		13,905			-		-		-	19,030	-	-	-
Pool Fiberglass	-	-		-,			40,289		-		-	-	-	-	-
Pool Tile/Coping	-	-	-	-	-	-			-		16,080	-	-	-	-
SPA HEATER	-	-	-	-	10,079	-	-		-			-	13,794	-	-
SPA FILTER				4,846										_	
SPA RE-TILE		_		4,040			_		_		_	_	_	_	
POOL DECKING	-	-	-	-	-		-	-	-	-	43,251	-	-	-	-
CABANA															
Shower Tile	-	-	-	-	-	-	-		-		-	-	-	-	-
BATH TILE	-	-	-	-	-	-	-		-		-	-	41,982	-	-
BATHROOMS REMODEL	-	-	-	-	-	-	-		-		-	-		-	-
SAUNA REMODEL													_	_	
SAUNA HEATER													_	_	
WATER HEATER	-	-	-	-	-		-		-	-	6,377	-	-	-	-
TERMITE TREATMENTS															
BLDG. 7606		_		_			_		_		_	25,662	_	_	_
BLDG. 7620, 7632		_					_				_	51,324	_	_	
BLDG. 7610, 7602		_					_				-	51,324	_	_	
BLDG. 7638, 7630	-	-	•	-	-	-	-	-	-	-	49,350	51,524	-	-	-
BLDG. 7634, 7628	-	-	-	-	•	•	•	•	-	•		-	-	-	-
BLDG. 7626	-	•		-	-	-	-	•	-	-	49,350	-	-	-	-
		-	18,030	-	-	-	-	-	-	-	•	-	-	-	-
Bldg.7636, 7640, 7624	50,009	-	-	-	-	-	-	-	-	-	-	-	-	-	-
FOUNDATION REPAIRS															
WATERPROOFING	-	-	-	-	490,812	-	-	-	-	-	-	-	-	-	-
FOUNDATION LEVELING	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
BALCONY INSPECTIONS	-	-	-	-	94,218	-	-	-	-	-	-	-	-	134,102	-
STRUCTURAL PLUMBING															
PLUMBING REPAIRS PARTIAL	-	-	-	-	-			-	-	-	-	-	-	-	

EUCALYPTUS GROVE HOA

PLUMBING REPAIRS PARTIAL -PLUMBING REPAIRS BALANCE -



12/28/2022

	EUCALYPTUS GROVE HOA														
RESERVE COMPONENT INVENTORY		THIRTY-YEAR PROJECTED ANNUAL RESERVE EXPENSES													
CATEGORY RESERVE COMPONENT	16 2038	17 2039	18 2040	19 2041	20 2042	21 2043	22 2044	23 2045	24 2046	25 2047	26 2048	27 2049	28 2050	29 2051	30 2052
BRIDGE REPAIRS	-	-	32,818	-	-	-	-	-	-	-	-	-	48,579	-	-
TREE TRIMMING	84,284	-	91,162	-	98,601	-	106,646	-	115,349	-	124,761	-	134,942	-	145,953
EXERCISE ROOM REMODEL EQUIPMENT	-	-	-	-	65,734 43,822	-	-			-	-	-	-	-	- 64,868
LIGHTING Large Street Fixtures Staircase LED Fixtures Carport Lights Medium Bollard Lights				- - -			- 37,919 - -			- - -	- - 35,488 -		134,342 - - -		- - - 40,542
MAILBOXES MAILBOXES & PAGODAS		-	-												
LANDSCAPE REFURBISH	-	171,415	-	-	192,819	-	-	216,895	-	-	243,977	-	-	274,441	-

12/28/2022

CONTINGENCY: 0% TOTALS: 417,675 198,101 1,272,618 74,372 1,852,595 346,145 2,184,828 1,337,108 210,447 87,439 3,151,744 375,703 498,684 436,299 2,046,584

EUCALYPTUS GROVE HOA										
Reserve Component Current Fiscal Year End: December 31, 2022 Inventory Number of units: 179										
			Repair /			Straight-Line	IDEAL	Projected		DEFICIT REDUCTION
CATEGORY	Unit	UNIT	REPLACE	USEFUL	RMNG.	ANNUAL	BALANCE	BALANCE		ANNUAL
RESERVE COMPONENT	QUANTITY TYPE	Cost	Cost	LIFE	LIFE	CONTRIBUTION	@F.Y.E.2022	@F.Y.E.2022	DEFICIT	CONTRIBUTION

NET INTEREST ON RESERVE SAVINGS :	1%
30-YEAR AVERAGE INFLATION RATE :	4%
INCREASE TO ANNUAL RESERVE CONTRIBUTION:	4%

Balance Forecast Type	ANNUAL CONTRIBUTION
CURRENT ANNUAL CONTRIBUTION	351,192
Straight-Line Annual Contribution	409,679
DEFICIT REDUCTION ANNUAL CONTRIBUTION	476,202
(Cash-Flow) Minimum Annual Contribution	389,856



						Εu	CALY	PTU	s Gr	OVE	HOA					
RESERVE COMPONENT INVENTORY	7															
	THIRTY-YEAR PROJECTED ANNUAL RESERVE EXPENSES															
CATEGORY Reserve Component	0 2022	1 2023	2 2024	3 2025	4 2026	5 2027	6 2028	7 2029	8 2030	9 2031	10 2032	11 2033	12 2034	13 2035	14 2036	15 2037

BALANCE FORECAST TYPE

THIRTY-YEAR PROJECTED ANNUAL RESERVE BALANCES

CURRENT

ANNUAL CONTRIBUTION 2,540,000 2,114,798 1,427,534 1,297,663 1,584,453 1,884,696 644,222 1,052,036 643,182 966,586 532,475 660,477 926,767 1,338,306 105,074 483,665

STRAIGHT-LINE

ANNUAL CONTRIBUTION 2,540,000 2,173,578 1,550,478 1,487,955 1,845,411 2,219,778 1,057,030 1,546,322 1,222,855 1,635,716 1,295,305 1,521,423 1,890,431 2,409,479 1,288,745 1,785,032

DEFICIT REDUCTION

ÅNNUAL CONTRIBUTION 2,540,000 2,240,433 1,690,313 1,704,392 2,142,225 2,600,900 1,526,557 2,108,521 1,882,173 2,396,784 2,162,946 2,500,662 2,986,501 3,627,829 2,635,051 3,265,205

(Cash-Flow) Minimum

ANNUAL CONTRIBUTION 2,540,000 2,153,655 1,508,808 1,423,459 1,756,964 2,106,207 917,115 1,378,792 1,026,384 1,408,925 1,036,756 1,229,619 1,563,812 2,046,422 887,559 1,343,954



EUCALYPTUS GROVE HOA Reserve Component INVENTORY THIRTY-YEAR PROJECTED ANNUAL RESERVE EXPENSES CATEGORY **RESERVE COMPONENT**

Balance Forecast Type		THIRTY-YEAR PROJECTED ANNUAL RESERVE BALANCES													
CURRENT ANNUAL CONTRIBUTION	729,804	1,225,517	673,799	1,349,402	274,390	733,545	-618,414	-1,098,475	-416,246	432,616	-1,752,023	-1,129,445	-583,531	72,874	-838,463
STRAIGHT-LINE Annual Contribution	2,154,277	2,778,732	2,361,623	3,177,943	2,250,010	2,862,866	1,671,503	1,359,216	2,216,691	3,248,579	1,255,065	2,077,196	2,831,439	3,705,307	3,020,939
DEFICIT REDUCTION ANNUAL CONTRIBUTION	3,774,471	4,545,356	4,281,350	5,257,723	4,497,077	5,284,752	4,276,051	4,154,589	5,211,389	6,451,451	4,675,321	5,724,424	6,715,620	7,836,829	7,410,616
(Cash-Flow) Minimum Annual Contribution	1,671,474	2,252,294	1,789,561	2,558,188	1,580,405	2,141,167	895,372	526,220	1,324,299	2,294,153	235,860	990,356	1,673,989	2,474,151	1,712,856









PAINTING: Wood Siding / Wood & Metal Trim / DryRot Repairs



EUCALYPTUS GROVE HOA










DECKING: Stair Landing ReSeal / ReSurface










PRIVACY / FENCING: Metal Pool Fence 6'



J.D. BROOKS








POOL AREA: Pool Heater / Filter








EXERCISE ROOM: Equipment / Remodel




LIGHTING: Large Street Fixtures





LIGHTING: Medium Bollard Lights



EUCALYPTUS GROVE HOA

	ROOFING								
<u>Cor</u>	mp.S:7626,7630,7634								
Quantity: Estimated Total Cost to Replace: Useful Life: Remaining Life:	3 Bldg. \$ 117,000 25 9								
Straight-Line Annual Contribution:	\$ 4,680								
Cost Source:	Previous Association Expenditure / Allowance								
	2 Bldg.								
Quantity: Estimated Total Cost to Replace: Useful Life: Remaining Life:	\$ 78,000 25 12								
Straight-Line Annual Contribution: Cost Source:	\$ 3,120 Previous Association Expenditure / Allowance								
	Comp.S: 7636, 7638								
Quantity:	2 Bldg.								
Estimated Total Cost to Replace:	\$ 78,000								
Useful Life:	25								
Remaining Life:	13								
Straight-Line Annual Contribution:	\$ 3,120								
Cost Source:	Previous Association Expenditure / Allowance								
<u>Cor</u>	mp.S:7602,7606,7610								
Quantity:	3 Bldg.								
Estimated Total Cost to Replace:	\$ 117,000								
Useful Life:	25								
Remaining Life:	14								
Straight-Line Annual Contribution: Cost Source:	\$ 4,680 Previous Association Expenditure / Allowance								
	-								
	mp.S:7620,7632,7640								
Quantity: Estimated Total Cost to Replace:	3 Bldg. \$ 117,000								
Useful Life:	25								
Remaining Life:	15								
Straight-Line Annual Contribution:	\$ 4,680								
Cost Source:	Previous Association Expenditure / Allowance								
Co	omp.S: Pool Cabana								
Quantity:	1 Bldg.								
Estimated Total Cost to Replace:	\$ 5,800								
Useful Life:	25								
Remaining Life:	15								
Straight-Line Annual Contribution:	\$ 232								
Cost Source:	Previous Association Expenditure / Allowance								
Quantity:	<u>Metal Carports</u> 30,000 SqFt								
Estimated Total Cost to Replace:	\$ 276,000								
Useful Life:	30								
Remaining Life:	1								
Straight-Line Annual Contribution:	\$ 9,200								
Cost Source:	JDB Cost Database								

Useful Life: 30 Remaining Life: 27 \$ **Straight-Line Annual Contribution:** 2,640 **Cost Source: JDB Cost Database** PAINTING Wood Siding Quantity: 120,000 SqFt **Estimated Total Cost to Replace:** \$ 168,000 6 Useful Life: 2 **Remaining Life: Straight-Line Annual Contribution:** \$ 28,000 **JDB Cost Database Cost Source:** Wood & Metal Trim 35.000 Quantity: SqFt **Estimated Total Cost to Replace:** \$ 73,500 **Useful Life:** 4 2 **Remaining Life: Straight-Line Annual Contribution:** \$ 18,375 **Cost Source:** JDB Cost Database Carports Quantity: 60,000 SqFt **Estimated Total Cost to Replace:** \$ 96,000 Useful Life: 6 2 **Remaining Life: Straight-Line Annual Contribution:** \$ 16,000 **JDB Cost Database Cost Source:** Metal Fence & Rail 4,000 Quantity: SqFt **Estimated Total Cost to Replace:** \$ 6,400 **Useful Life:** 4 1 **Remaining Life:** \$ **Straight-Line Annual Contribution:** 1,600 **Cost Source: JDB Cost Database** Front Wood Fence 600 Quantity: LnFt **Estimated Total Cost to Replace:** \$ 6,900 **Useful Life:** 4 **Remaining Life:** 4 **Straight-Line Annual Contribution:** \$ 1.725 **JDB Cost Database Cost Source:** Wood Dry Rot Repairs Quantity: 1 Allow \$ 480,000 **Estimated Total Cost to Replace:** 4 Useful Life: 2 **Remaining Life:**

Straight-Line Annual Contribution:

Cost Source:

Gutter & Downspouts

LnFt

7,200

Estimated Total Cost to Replace: \$ 79,200

Quantity:

RESERVE STUDIES

120,000

Previous Association Expenditure / Allowance

\$

<u> </u>	000	builty Replace
Quantity:	1	Allow
Estimated Total Cost to Replace:	\$	454,500
Useful Life:	20	
Remaining Life:	3	
Straight-Line Annual Contribution:	\$	22,725
Cost Source:	Prev	vious Association Expenditure / Allowance

Wood Siding Replace

PAVING	ì
--------	---

As	sphalt	Seal & F	Repair
Quantity:	120,	000	SqFt
Estimated Total Cost to Replace:	\$	26,400	
Useful Life:	3		
Remaining Life:	1		
Straight-Line Annual Contribution:	\$	8,800	
Cost Source:	JDB	Cost Data	lbase
	<u>Aspl</u>	nalt Over	lay
Quantity:	120,	000	SqFt
Estimated Total Cost to Replace:	\$	264,000	
Useful Life:	25		
Remaining Life:	22		
Straight-Line Annual Contribution:	\$	10,560	
Cost Source:	JDB	Cost Data	lbase
	<u>Conc</u>	rete Rep	<u>airs</u>
Quantity:	1		Allow
Estimated Total Cost to Replace:	\$	65,000	
Useful Life:	5		
Remaining Life:	1		
Straight-Line Annual Contribution:	\$	13,000	
Cost Source:	Prev	vious Vend	lor Proposal

DECKING

Sta	air Lar	nding ReSeal
Quantity:	4,600	SqFt
Estimated Total Cost to Replace:	\$	27,600
Useful Life:	5	
Remaining Life:	1	
Straight-Line Annual Contribution:	\$	5,520
Cost Source:	JDB C	ost Database
<u>Stai</u>	r Land	ing ReSurface
Quantity:	4,600	SqFt
Estimated Total Cost to Replace:	\$	52,900
Useful Life:	20	
Remaining Life:	1	
Straight-Line Annual Contribution:	\$	2,645
Cost Source:	JDB C	ost Database



Mie	d-Lar	<u>ndings> Trex</u>
Quantity:	7	Allow
Estimated Total Cost to Replace:	\$	7,000
Useful Life:	30	
Remaining Life:	1	
Straight-Line Annual Contribution:	\$	233
Cost Source:	Prev	ious Association Expenditure / Allowance
Ī	rex N	<u>lid-Landings</u>
Quantity:	24	Allow
Estimated Total Cost to Replace:	\$	24,000
Useful Life:	30	
Remaining Life:	24	

Straight-Line Annual Contribution: \$

\$ 800

Cost Source: Previous Association Expenditure / Allowance

PRIVACY / FENCING

	<u>lı</u>	<u>ntercom</u>		
Quantity:	1	Unit		
Estimated Total Cost to Replace:	\$	6,200		
Useful Life:	15			
Remaining Life:	9			
Straight-Line Annual Contribution:	\$	413		
Cost Source:	Prev	vious Association Expenditure / Allowance		
Front Gate Wiring				
Quantity:	1	Allow		
Estimated Total Cost to Replace:	\$	9,000		
Useful Life:	10			
Remaining Life:	6			
Straight-Line Annual Contribution:	\$	900		
Cost Source:	Prev	vious Association Expenditure / Allowance		
Ga	ate O	<u>perators (Roll)</u>		
Quantity:	2	Unit		
Estimated Total Cost to Replace:	\$	8,000		
Useful Life:	10			
Remaining Life:	6			
Straight-Line Annual Contribution:	\$	800		
Cost Source:	JDB	Cost Database / Allowance		
<u>\</u>	<u>/ehic</u>	le Roll Gates		
Quantity:	2	Unit		
Estimated Total Cost to Replace:	\$	9,200		
Useful Life:	30			
Remaining Life:	5			
Straight-Line Annual Contribution:	\$	307		
Cost Source:	JDB	Cost Database / Allowance		
	Key F	Fob Readers		
Quantity:	3	Unit		
Estimated Total Cost to Replace:	\$	8,400		
Useful Life:	12			
Remaining Life:	4			
Straight-Line Annual Contribution:	\$	700		
Cost Source:	JDB	Cost Database / Allowance		

	Gate	e Keypa	<u>ds</u>	
Quantity:	2		Unit	
Estimated Total Cost to Replace:	\$	4,800		
Useful Life:	15			
Remaining Life:	2			
Straight-Line Annual Contribution:	\$	320		
Cost Source:	JDB	Cost Data	base / Allowance	
<u>F</u>	Front V	Wood Fe	ence	
Quantity:	600		LnFt	
Estimated Total Cost to Replace:	\$	120,000		
Useful Life:	20			
Remaining Life:	20			
Straight-Line Annual Contribution:	\$	6,000		
Cost Source:	Previ	ious Asso	ciation Expenditure / A	llowance
N		ool Fen		
Quantity:	180		LnFt	
Estimated Total Cost to Replace:	\$	12,600		
Useful Life:	25			
Remaining Life:	15			
Straight-Line Annual Contribution:	\$	504		
Cost Source:	JDB	Cost Data	base	
	Stair	Rails 3.	5'	
Quantity:	500		LnFt	
Estimated Total Cost to Replace:	\$	19,000		
Useful Life:	30			
Remaining Life:	7			
Straight-Line Annual Contribution:	\$	633		
Cost Source:	JDB	Cost Data	base	
	Wood	Rail Fe	nce	
Quantity:	450		LnFt	
Estimated Total Cost to Replace:	\$	10,800		
Useful Life:	30			
Remaining Life:	12			
Straight-Line Annual Contribution:	\$	360		
Cost Source:	-	Cost Data	base	
		Utility Do		
- Quantity:	472		Unit	
Estimated Total Cost to Replace:	\$	236,000		
Useful Life:	45	- ,		
Remaining Life:	8			
Straight-Line Annual Contribution:	\$	5,244		
Cost Source:	•		base / Allowance	

POOL AREA

Pool Heater

Quantity:	1	Unit
Estimated Total Cost to Replace:	\$	4,600
Useful Life:	8	
Remaining Life:	2	
Straight-Line Annual Contribution:	\$	575
Cost Source:	JDB (Cost Database

	Pool Filter
Quantity:	1 Unit
Estimated Total Cost to Replace:	\$ 2,500
Useful Life:	12
Remaining Life:	5
Straight-Line Annual Contribution:	\$ 208
Cost Source:	JDB Cost Database
I	Pool & Spa Pumps
Quantity:	3 Unit
Estimated Total Cost to Replace:	\$ 6,600
Useful Life:	8
Remaining Life:	3
Straight-Line Annual Contribution:	\$ 825
Cost Source:	JDB Cost Database
	Pool Fiberglass
Quantity:	1,000 SqFt
Estimated Total Cost to Replace:	\$ 17,000
Useful Life:	18
Remaining Life:	4
Straight-Line Annual Contribution:	\$ 944
Cost Source:	JDB Cost Database
	Pool Tile/Coping
Quantity:	100 LnFt
Estimated Total Cost to Replace:	\$ 5,800
Useful Life:	20
Remaining Life:	6
Straight-Line Annual Contribution:	\$ 290
Cost Source:	JDB Cost Database
	Spa Heater
Quantity:	1 Unit
Estimated Total Cost to Replace:	\$ 4,600
Useful Life:	8
Remaining Life:	4
Straight-Line Annual Contribution: Cost Source:	\$
	Spa Filter
Quantity:	1 Unit
Estimated Total Cost to Replace:	\$ 2,300
Useful Life:	12
Remaining Life:	7
Straight-Line Annual Contribution:	\$ 192
Cost Source:	JDB Cost Database
	Spa Re-Tile
Quantity:	1 Unit
Estimated Total Cost to Replace:	\$ 8,700
Useful Life:	40
Remaining Life:	3
Straight-Line Annual Contribution:	\$ 218
Cost Source:	Allowance
	-

	Poo	ol Decking
Quantity:	1	Allow
Estimated Total Cost to Replace:	\$	15,600
Useful Life:	20	
Remaining Life:	6	
Straight-Line Annual Contribution:	\$	780
Cost Source:	Prev	vious Association Expenditure / Allowance

	C	ABAN	A			
Shower Tile						
Quantity:	1		<u>Allow</u>			
Estimated Total Cost to Replace:	\$	10,000				
Useful Life:	30	•				
Remaining Life:	1					
Straight-Line Annual Contribution:	\$	333				
Cost Source:	Allo	wance				
	E	Bath Tile				
Quantity:	1		Allow			
Estimated Total Cost to Replace:	\$	14,000				
Useful Life:	30					
Remaining Life:	28					
Straight-Line Annual Contribution:	\$	467				
Cost Source:	Prev	vious Asso	ciation Expenditure / Allowance			
Ba	Bathrooms Remodel					
Quantity:	2		Allow			
Estimated Total Cost to Replace:	\$	10,000				
Useful Life:	30					
Remaining Life:	4					
Straight-Line Annual Contribution:	\$	333				
Cost Source:		wance				
Sauna Remodel						
Quantity:	1	-	Allow			
Estimated Total Cost to Replace:	\$	7,200				
Useful Life:	20					
Remaining Life:	15 ¢	260				
Straight-Line Annual Contribution: Cost Source:	\$ Broy	360 Vious Asso	ciation Exponditure / Allowance			
Cost Source:			ciation Expenditure / Allowance			
0		una Heat				
Quantity:	1	2 000	Unit			
Estimated Total Cost to Replace:	\$ 20	3,800				
Useful Life: Romaining Life:	20 11					
Remaining Life: Straight-Line Annual Contribution:	\$	190				
Cost Source:	-		base / Allowance			
0		ater Heate	<u>er</u> Unit			
Quantity: Estimated Total Cost to Replace:	1 \$	2,300	Unit			
Estimated Total Cost to Replace: Useful Life:	э 15	∠,300				
Remaining Life:	11					
Straight-Line Annual Contribution:	\$	153				
Cost Source:	-		base / Allowance			

TERMITE TREATMENTS

All Buildings

Quantity:13\$ 8,900Estimated Total Cost to Replace:\$ 115,700Useful Life:15Remaining Life:1-12Straight-Line Annual Contribution:\$ 7,709Cost Source:Previous Association Expenditure / Allowance

FOUNDATION REPAIRS

Waterproofing

	vval	erproon	ng	
Quantity:	1		Allow	
Estimated Total Cost to Replace:	\$	224,000		
Useful Life:	30			
Remaining Life:	20			
Straight-Line Annual Contribution:	\$	7,467		
Cost Source:	Prev	ious Asso	ciation Expenditure / Allowance	
Foundation Leveling				
Quantity:	1		Allan	
Quantity.			Allow	
Estimated Total Cost to Replace:	\$	108,000	Allow	
		108,000	Allow	
Estimated Total Cost to Replace:	\$	108,000	Allow	

Cost Source: Previous Vendor Estimate

Allow

BALCONY INSPECTIONS

Cost Source:	Allo	wance
Straight-Line Annual Contribution:	\$	4,778
Remaining Life:	2	
Useful Life:	9	
Estimated Total Cost to Replace:	\$	43,000
Quantity:	1	

STRUCTURAL PLUMBING

Plumbing Repairs Partial

Quantity:	1	Allow
Estimated Total Cost to Replace:	\$	110,000
Useful Life:	35	
Remaining Life:	1	
Straight-Line Annual Contribution:	\$	3,143
Cost Source:	Prev	vious Vendor Estimate
<u>Plum</u>	bing	Repairs Balance
<u>Plum</u> Quantity:	bing 1	Repairs Balance Allow
	-	
Quantity:	1	Allow
Quantity: Estimated Total Cost to Replace:	1 \$	Allow

Cost Source: Previous Vendor Estimate

J.D. BROOKS
RESERVE STUDIES

BRIDGE REPAIRS Allow Quantity: 1 \$ **Estimated Total Cost to Replace:** 16,200 Useful Life: 10 **Remaining Life:** 8 \$ 1,620 **Straight-Line Annual Contribution:** Cost Source: Previous Association Expenditure / Allowance

TREE TRIMMING

45,000

- 2 Quantity: **Estimated Total Cost to Replace:** 2 Useful Life:
 - **Remaining Life:** 2

Cost Source:

Straight-Line Annual Contribution:

\$ 22,500

\$

Previous Association Expenditure / Allowance

Allow

EXERCISE ROOM

Remodel

Quantity:	1		Allow
Estimated Total Cost to Replace:	\$	30,000	
Useful Life:	20		
Remaining Life:	20		
Straight-Line Annual Contribution:	\$	1,500	
Cost Source:	Allowance		
	<u>Equipment</u>		
	<u>E0</u>	Juipmen	
Quantity:	1	Juipment	<u>Allow</u>
Quantity: Estimated Total Cost to Replace:		20,000	
	1		
Estimated Total Cost to Replace:	1 \$		
Estimated Total Cost to Replace: Useful Life:	1 \$ 10		
Estimated Total Cost to Replace: Useful Life: Remaining Life:	1 \$ 10 10 \$	20,000	

LIGHTING

Large Street Fixtures Unit Quantity: 14 **Estimated Total Cost to Replace:** \$ 44,800 Useful Life: 30 **Remaining Life:** 28 **Straight-Line Annual Contribution:** \$ 1.493 **Cost Source: Previous Association Expenditure / Allowance** Staircase LED Fixtures Quantity: 1 Allow **Estimated Total Cost to Replace:** \$ 16,000 **Useful Life:** 25 22 Remaining Life: **Straight-Line Annual Contribution:** \$ 640 Cost Source: **Previous Association Expenditure / Allowance**



	Carport Lights			
Quantity:	64	Unit		
Estimated Total Cost to Replace:	\$	12,800		
Useful Life:	25			
Remaining Life:	1			
Straight-Line Annual Contribution:	\$	512		
Cost Source:	JDB	Cost Database / Allowand	e	
Medium Bollard Lights				
inie	aium	i Bollard Lights		
<u>ivie</u> Quantity:	<u>aium</u> 50	Unit		
Quantity:	50	Unit		
Quantity: Estimated Total Cost to Replace:	50 \$	Unit		
Quantity: Estimated Total Cost to Replace: Useful Life:	50 \$ 25	Unit		

MAILBOXES

Mailboxes & Pagodas

Quantity:	200	Unit
Estimated Total Cost to Replace:	\$	40,000
Useful Life:	30	
Remaining Life:	1	
Straight-Line Annual Contribution:	\$	1,333
Cost Source:	JDB Cost Database / Allowance	
	022	

LANDSCAPE REFURBISH

Quantity:	1		Allow
Estimated Total Cost to Replace:	\$	88,000	
Useful Life:	3		
Remaining Life:	2		
Straight-Line Annual Contribution:	\$	29,333	
Cost Source:	Allowance		



Civil Code §5300. Annual Budget Report.

(a) Notwithstanding a contrary provision in the governing documents, an association shall distribute an annual budget report 30 to 90 days before the end of its fiscal year.

(b) Unless the governing documents impose more stringent standards, the annual budget report shall include all of the following information:

(1) A pro forma operating budget, showing the estimated revenue and expenses on an accrual basis.

(2) A summary of the association's reserves, prepared pursuant to Section 5565.

(3) A summary of the reserve funding plan adopted by the board, as specified in paragraph
(5) of subdivision (b) of Section 5550. The summary shall include notice to members that the full reserve study plan is available upon request, and the association shall provide the full reserve plan to any member upon request.

(4) A statement as to whether the board has determined to defer or not undertake repairs or replacement of any major component with a remaining life of 30 years or less, including a justification for the deferral or decision not to undertake the repairs or replacement.

(5) A statement as to whether the board, consistent with the reserve funding plan adopted pursuant to **Section 5560**, has determined or anticipates that the levy of one or more special assessments will be required to repair, replace, or restore any major component or to provide adequate reserves therefor. If so, the statement shall also set out the estimated amount, commencement date, and duration of the assessment.

(6) A statement as to the mechanism or mechanisms by which the board will fund reserves to repair or replace major components, including assessments, borrowing, use of other assets, deferral of selected replacements or repairs, or alternative mechanisms.

(7) A general statement addressing the procedures used for the calculation and establishment of those reserves to defray the future repair, replacement, or additions to those major components that the association is obligated to maintain. The statement shall include, but need not be limited to, reserve calculations made using the formula described in paragraph (4) of subdivision (b) of **Section 5570**, and may not assume a rate of return on cash reserves in excess of 2 percent above the discount rate published by the Federal Reserve Bank of San Francisco at the time the calculation was made.

(8) A statement as to whether the association has any outstanding loans with an original term of more than one year, including the payee, interest rate, amount outstanding, annual payment, and when the loan is scheduled to be retired.

(9) A summary of the association's property, general liability, earthquake, flood, and fidelity insurance policies. For each policy, the summary shall include the name of the insurer, the type of insurance, the policy limit, and the amount of the deductible, if any. To the extent that any of the required information is specified in the insurance policy declaration page, the association may meet its obligation to disclose that information by making copies of that page and distributing it with the annual budget report. The summary distributed pursuant to this paragraph shall contain, in at least 10-point boldface type, the following statement: This summary of the association's policies of insurance provides only certain information, as required by Section 5300 of the Civil Code, and should not be considered a substitute for the complete policy terms and conditions contained in the actual policies of insurance. Any association member may, upon request and provision of reasonable notice, review the association's insurance policies and, upon request and payment of reasonable duplication charges, obtain copies of those policies. Although the association maintains the policies of insurance specified in this summary, the association's policies of insurance may not cover your property, including personal property or real property improvements to or around your dwelling, or personal injuries or other losses that occur within or around your dwelling. Even if a loss is covered, you may nevertheless be responsible for paying all or a portion of any deductible that applies. Association members should consult with their individual insurance broker or agent for appropriate additional coverage.

(c) The annual budget report shall be made available to the members pursuant to **Section 5320**.

(d) The summary of the association's reserves disclosed pursuant to paragraph (2) of subdivision (b) shall not be admissible in evidence to show improper financial management of an association, provided that other relevant and competent evidence of the financial condition of the association is not made inadmissible by this provision.

(e) The Assessment and Reserve Funding Disclosure Summary form, prepared pursuant to **Section 5570**, shall accompany each annual budget report or summary of the annual budget report that is delivered pursuant to this article.

Civil Code §5550. Visual Inspection of Major Components.

(a) At least once every three years, the board shall cause to be conducted a reasonably competent and diligent visual inspection of the accessible areas of the major components that the association is obligated to repair, replace, restore, or maintain as part of a study of the reserve account requirements of the common interest development, if the current replacement value of the major components is equal to or greater than one-half of the gross budget of the association, excluding the association's reserve account for that period. The board shall review this study, or cause it to be reviewed, annually and shall consider and implement necessary adjustments to the board's analysis of the reserve account requirements as a result of that review.

(b) The study required by this section shall at a minimum include:

(1) Identification of the major components that the association is obligated to repair, replace, restore, or maintain that, as of the date of the study, have a remaining useful life of less than 30 years.

(2) Identification of the probable remaining useful life of the components identified in paragraph (1) as of the date of the study.

(3) An estimate of the cost of repair, replacement, restoration, or maintenance of the components identified in paragraph (1).

(4) An estimate of the total annual contribution necessary to defray the cost to repair, replace, restore, or maintain the components identified in paragraph (1) during and at the end of their useful life, after subtracting total reserve funds as of the date of the study.

(5) A reserve funding plan that indicates how the association plans to fund the contribution identified in paragraph (4) to meet the association's obligation for the repair and replacement of all major components with an expected remaining life of 30 years or less,

not including those components that the board has determined will not be replaced or repaired.

Civil Code §5560. Reserve Funding Plan.

(a) The reserve funding plan required by **Section 5550** shall include a schedule of the date and amount of any change in regular or special assessments that would be needed to sufficiently fund the reserve funding plan.

(b) The plan shall be adopted by the board at an open meeting before the membership of the association as described in Article 2 (commencing with **Section 4900**) of Chapter 6.

(c) If the board determines that an assessment increase is necessary to fund the reserve funding plan, any increase shall be approved in a separate action of the board that is consistent with the procedure described in **Section 5605**.

Civil Code §5565. Summary of Association Reserves.

The summary of the association's reserves required by paragraph (2) of subdivision (b) of **Section 5300** shall be based on the most recent review or study conducted pursuant to **Section 5550**, shall be based only on assets held in cash or cash equivalents, shall be printed in boldface type, and shall include all of the following:

(a) The current estimated replacement cost, estimated remaining life, and estimated useful life of each major component.

(b) As of the end of the fiscal year for which the study is prepared:

(1) The current estimate of the amount of cash reserves necessary to repair, replace, restore, or maintain the major components.

(2) The current amount of accumulated cash reserves actually set aside to repair, replace,

restore, or maintain major components.

(3) If applicable, the amount of funds received from either a compensatory damage award or settlement to an association from any person for injuries to property, real or personal, arising out of any construction or design defects, and the expenditure or disposition of funds, including the amounts expended for the direct and indirect costs of repair of construction or design defects. These amounts shall be reported at the end of the fiscal year for which the study is prepared as separate line items under cash reserves pursuant to paragraph (2). Instead of complying with the requirements set forth in this paragraph, an association that is obligated to issue a review of its financial statement pursuant to **Section 5305** may include in the review a statement containing all of the information required by this paragraph.

(c) The percentage that the amount determined for purposes of paragraph (2) of subdivision(b) equals the amount determined for purposes of paragraph (1) of subdivision (b).

(d) The current deficiency in reserve funding expressed on a per unit basis. The figure shall be calculated by subtracting the amount determined for purposes of paragraph (2) of subdivision (b) from the amount determined for purposes of paragraph (1) of subdivision (b) and then dividing the result by the number of separate interests within the association, except that if assessments vary by the size or type of ownership interest, then the association shall calculate the current deficiency in a manner that reflects the variation.